SMART HOME MONITORING



Motion Sensor

Manufacturer's Installation Guide



Mounting

Height: 1.8-2.4m. For pet rejection, the optimal height is 2.1m.

Installation Options: Surface or Corner


General Guidance:


- 1. Keep away from heat sources.
- 2. Do not expose to air drafts.
- 3. Do not install outdoors.
- 4. Avoid direct sunshine.
- 5. Do not install near high-voltage electrical lines.
- 6. Do not install behind partitions.
- 7. Mount on solid stable surface.

Installation Procedure:


Note: Pairing should be performed before installation.

- 1. Press in this point.
- 2. Push in the direction of the arrow shown in the drawing to separate the detector from the bracket.





- 3. Mount the bracket on the wall.
 - Use $(\mathbf{A1})$ or $(\mathbf{A2})$ for corner mounting.
 - Use **B** for surface mounting.



- **4.** Mount the detector on the bracket by sliding it downward until a click is heard.
- 5. Keep the protective file on the unit until after the unit is mounted in its final location. Then remove it.